

TOOL MODEL : STEALTH 4 W/HEX LINK

PRESSURE / TORQUE CONVERSION CHART

| Pressure in PSI | FT. LBS | Torque in KGM | NM | Pressure in BAR |
|---------------------------|----------------|-------------------------|-----------|---------------------------|
| 1500 | 604 | 84 | 819 | 104 |
| 1600 | 644 | 89 | 874 | 110 |
| 1800 | 725 | 100 | 983 | 124 |
| 2000 | 806 | 111 | 1093 | 138 |
| 2200 | 885 | 122 | 1200 | 152 |
| 2400 | 964 | 133 | 1307 | 165 |
| 2600 | 1043 | 144 | 1414 | 179 |
| 2800 | 1122 | 155 | 1521 | 193 |
| 3000 | 1201 | 166 | 1628 | 207 |
| 3200 | 1281 | 177 | 1737 | 220 |
| 3400 | 1361 | 188 | 1846 | 234 |
| 3600 | 1442 | 199 | 1954 | 248 |
| 3800 | 1522 | 210 | 2063 | 262 |
| 4000 | 1602 | 222 | 2172 | 276 |
| 4200 | 1680 | 232 | 2278 | 290 |
| 4400 | 1758 | 243 | 2384 | 303 |
| 4600 | 1837 | 254 | 2490 | 317 |
| 4800 | 1915 | 265 | 2596 | 331 |
| 5000 | 1993 | 276 | 2702 | 345 |
| 5200 | 2075 | 287 | 2813 | 358 |
| 5400 | 2157 | 298 | 2925 | 372 |
| 5600 | 2240 | 310 | 3036 | 386 |
| 5800 | 2322 | 321 | 3147 | 400 |
| 6000 | 2404 | 332 | 3259 | 414 |
| 6200 | 2485 | 344 | 3369 | 427 |
| 6400 | 2566 | 355 | 3478 | 441 |
| 6600 | 2647 | 366 | 3588 | 455 |
| 6800 | 2728 | 377 | 3698 | 468 |
| 7000 | 2809 | 388 | 3808 | 482 |
| 7200 | 2887 | 399 | 3913 | 496 |
| 7400 | 2965 | 410 | 4019 | 510 |
| 7600 | 3042 | 421 | 4124 | 524 |
| 7800 | 3120 | 432 | 4230 | 538 |
| 8000 | 3198 | 442 | 4335 | 552 |
| 8200 | 3280 | 454 | 4446 | 565 |
| 8400 | 3362 | 465 | 4558 | 579 |
| 8600 | 3444 | 476 | 4669 | 593 |
| 8800 | 3526 | 488 | 4780 | 607 |
| 9000 | 3608 | 499 | 4891 | 620 |
| 9200 | 3690 | 510 | 5003 | 634 |
| 9400 | 3773 | 522 | 5114 | 648 |
| 9600 | 3855 | 533 | 5226 | 662 |
| 9800 | 3938 | 545 | 5338 | 676 |
| 10000 | 4020 | 556 | 5450 | 690 |