



TOOL MODEL : 2XLCT

PRESSURE / TORQUE CONVERSION CHART

| Pressure in PSI | FT. LBS | Torque in KGM | NM | Pressure in BAR |
|---------------------------|----------------|-------------------------|-----------|---------------------------|
|---------------------------|----------------|-------------------------|-----------|---------------------------|

| | | | | |
|-------|------|-----|------|-----|
| 1500 | 255 | 35 | 346 | 104 |
| 1600 | 272 | 38 | 369 | 110 |
| 1800 | 306 | 42 | 415 | 124 |
| 2000 | 340 | 47 | 461 | 138 |
| 2200 | 376 | 52 | 510 | 152 |
| 2400 | 412 | 57 | 559 | 165 |
| 2600 | 448 | 62 | 607 | 179 |
| 2800 | 484 | 67 | 656 | 193 |
| 3000 | 520 | 72 | 705 | 207 |
| 3200 | 552 | 76 | 748 | 220 |
| 3400 | 584 | 81 | 792 | 234 |
| 3600 | 616 | 85 | 835 | 248 |
| 3800 | 648 | 90 | 878 | 262 |
| 4000 | 680 | 94 | 922 | 276 |
| 4200 | 714 | 99 | 968 | 290 |
| 4400 | 748 | 103 | 1014 | 303 |
| 4600 | 782 | 108 | 1060 | 317 |
| 4800 | 816 | 113 | 1106 | 331 |
| 5000 | 850 | 118 | 1152 | 345 |
| 5200 | 884 | 122 | 1198 | 358 |
| 5400 | 918 | 127 | 1244 | 372 |
| 5600 | 952 | 132 | 1291 | 386 |
| 5800 | 986 | 136 | 1337 | 400 |
| 6000 | 1020 | 141 | 1383 | 414 |
| 6200 | 1054 | 146 | 1429 | 427 |
| 6400 | 1088 | 150 | 1475 | 441 |
| 6600 | 1122 | 155 | 1521 | 455 |
| 6800 | 1156 | 160 | 1567 | 468 |
| 7000 | 1190 | 165 | 1613 | 482 |
| 7200 | 1224 | 169 | 1659 | 496 |
| 7400 | 1258 | 174 | 1705 | 510 |
| 7600 | 1292 | 179 | 1751 | 524 |
| 7800 | 1326 | 183 | 1798 | 538 |
| 8000 | 1360 | 188 | 1844 | 552 |
| 8200 | 1394 | 193 | 1890 | 565 |
| 8400 | 1428 | 197 | 1936 | 579 |
| 8600 | 1462 | 202 | 1982 | 593 |
| 8800 | 1496 | 207 | 2028 | 607 |
| 9000 | 1530 | 212 | 2074 | 620 |
| 9200 | 1566 | 217 | 2123 | 634 |
| 9400 | 1602 | 222 | 2172 | 648 |
| 9600 | 1638 | 227 | 2220 | 662 |
| 9800 | 1674 | 232 | 2269 | 676 |
| 10000 | 1710 | 236 | 2318 | 690 |