



TOOL MODEL : STEALTH 2 W/HEX LINK

PRESSURE / TORQUE CONVERSION CHART

Pressure in PSI	FT. LBS	Torque in KGM	NM	Pressure in BAR
1500	242	33	328	104
1600	259	36	351	110
1800	294	41	398	124
2000	328	45	445	138
2200	361	50	490	152
2400	394	55	535	165
2600	428	59	580	179
2800	461	64	625	193
3000	494	68	670	207
3200	529	73	717	220
3400	563	78	763	234
3600	598	83	810	248
3800	632	87	857	262
4000	667	92	904	276
4200	706	98	957	290
4400	745	103	1010	303
4600	784	108	1063	317
4800	823	114	1116	331
5000	862	119	1169	345
5200	896	124	1215	358
5400	930	129	1261	372
5600	964	133	1307	386
5800	998	138	1353	400
6000	1032	143	1399	414
6200	1073	148	1455	427
6400	1114	154	1510	441
6600	1155	160	1566	455
6800	1196	165	1621	468
7000	1237	171	1677	482
7200	1271	176	1722	496
7400	1304	180	1768	510
7600	1338	185	1814	524
7800	1371	190	1859	538
8000	1405	194	1905	552
8200	1443	200	1956	565
8400	1481	205	2008	579
8600	1520	210	2060	593
8800	1558	215	2112	607
9000	1596	221	2164	620
9200	1629	225	2208	634
9400	1662	230	2252	648
9600	1694	234	2297	662
9800	1727	239	2341	676
10000	1760	243	2386	690